

**A beautiful building that belies its years...  
but time, atmosphere and pollutants are catching up**



The alloy caps and powder coated style features are through weather, pollution, and time, these are progressively degenerating...

Leaching of this soil is now quite prevalent and it stains the windows.

**Building treatment is actually quite simple...**

Any badly soiled parts needing a spot clean with Tuff Prep™, a wash with Simple Prep™ and Right Rinse™ in combination then a final wash with the handy fire hose.

A three step sealing of the substrate ensuring on-going ease of maintenance.

The example below quite graphically shows the shine restored to the capping that

This test section being used as the "litmus" test of a high summer in Sydney Australia.



High Rise building maintenance is best undertaken by training individuals with all relevant safety equipment, licenses and training on the products to be applied. In Sydney, we recommend TOWNVIEW GROUP [service@townviewgroup.com.au](mailto:service@townviewgroup.com.au)